



Model Name	IPS-3106-SE-PB	Version	1.00.0F	Designer	Approval
Part Name	Firmware	Date	2021/04/07		
Part Number	N/A	Unit	N/A		
File Name	IPS-3106-SE-PB_Release note_1.00.0F_20210407.pdf				

## Release Note

FIRMWARE VERSION 1.00.0F .....	2
FIRMWARE VERSION 1.00.0E .....	2
FIRMWARE VERSION 1.00.0D .....	2
FIRMWARE VERSION 1.00.0C .....	2
FIRMWARE VERSION 1.00.0B .....	3
FIRMWARE VERSION 1.00.0A .....	3
FIRMWARE VERSION 1.00.09 .....	3
FIRMWARE VERSION 1.00.08 .....	3
FIRMWARE VERSION 1.00.07 .....	3
FIRMWARE VERSION 1.00.06 .....	4
FIRMWARE VERSION 1.00.05 .....	4
FIRMWARE VERSION 1.00.04 .....	4
FIRMWARE VERSION 1.00.03 .....	4
FIRMWARE VERSION 1.00.02 .....	5
FIRMWARE VERSION 1.00.01 .....	5
FIRMWARE VERSION 1.00.00 .....	5



## Firmware Version 1.00.0F

Date: 2021/04/07

New Feature / System Release	Description
N/A	N/A
Update	Description
System	Fixed memory leak issue.

## Firmware Version 1.00.0E

Date: 2019/05/14

New Feature / System Release	Description
N/A	N/A
Update	Description
Auto Backup	Add "NTP Status" for auto backup and modify auto backup configure file name.

## Firmware Version 1.00.0D

Date: 2019/05/07

New Feature / System Release	Description
N/A	N/A
Update	Description
Fast Redundancy Status	Fix the chain status display issue

## Firmware Version 1.00.0C

Date: 2019/05/03

New Feature / System Release	Description
Fast Redundancy Status	Add auto refresh button, topology status and packet statistics
Update	Description
N/A	N/A

## Firmware Version 1.00.0B

Date: 2019/04/02

New Feature / System Release	Description
Auto Backup	Add auto backup trigger condition with NTP time
Update	Description
N/A	N/A

## Firmware Version 1.00.0A

Date: 2019/01/02

New Feature / System Release	Description
Fast Redundancy	Add multicast stream copy function
Update	Description
N/A	N/A

## Firmware Version 1.00.09

Date: 2018/11/23

New Feature / System Release	Description
N/A	N/A
Update	Description
Fast Redundancy	Fixed that switch reboot randomly when topology change

## Firmware Version 1.00.08

Date: 2018/11/19

New Feature / System Release	Description
N/A	N/A
Update	Description
Fast Redundancy	Fixed that topology change will cause.

## Firmware Version 1.00.07

Date: 2018/08/16

New Feature / System Release	Description
N/A	N/A



Update	Description
Chain	Fixed that topology of chain is not stable.

## Firmware Version 1.00.06

Date: 2018/08/02

New Feature / System Release	Description
Fast Redundancy	Added that the fast redundancy note for chain protocol.
SNMP	Added that Fast Redundancy port Link Down Trap.
Update	Description
CLI	Fixed that when input a symbol "," to fast redundancy description, the symbol will disappear and the entry config will be changed.
WEB	Fixed that the function tree name of fast redundancy is not the same with the setting page title on the WEB.

## Firmware Version 1.00.05

Date: 2018/07/24

New Feature / System Release	Description
N/A	N/A
Update	Description
SNMP	Fixed that the SNMP trap will not startup when system boot up issue.

## Firmware Version 1.00.04

Date: 2018/07/20

New Feature / System Release	Description
Ring	Added that support Fast Ring v2 on WEB, CLI and SNMP.
Update	Description
CLI	Fixed that CLI will be hung when type "reload image" too many times.

## Firmware Version 1.00.03

Date: 2018/06/15

New Feature / System Release	Description
N/A	N/A
Update	Description
L2PT	Fixed that L2PT port can converter packet to designate MAC, but when



	other port receives designate MAC will not converter to original packet.
VLAN	Fixed that the CLI will be cut off after configuring Dot1q VLAN settings on DUT and checking the VLAN table in CLI.

## Firmware Version 1.00.02

Date: 2018/06/08

New Feature / System Release	Description
CPU temperature	Modify the default value of CPU threshold to 80°C from 40°C.
Power Budget	Modify the Power Budget calculation to meet the actual use.
Update	Description
CLI	Fixed that “show running-config interface 6,10”, it can’t showed vlan id 4094.
L2PT	Fixed that when L2PT work with IGMP snooping/DHCP snooping will cause DUT reboot or hang issue.

## Firmware Version 1.00.01

Date: 2018/04/25

New Feature / System Release	Description
CLI	Added that “show running configure” command can support to search with a specific word.
Update	Description
WEB	Fixed that the WEB page display issue when login fail.
RSTP	Fixed that RSTP process will random crash issue, when RSTP topology is changed.
CLI	Fixed that it is fail when typing "no switch statistics polling port" command.
CLI	Fixed that the default value is not correct when typing “no poe total-budget”.

## Firmware Version 1.00.00

Date: 2018/04/17

New Feature / System Release	Description
N/A	The Official Version
Update	Description
N/A	N/A

