

Model Name	MCT-RACK-Series-MGM	Version	1.02.0I	Designer	Approval
Part Name	Firmware	Date	2020/03/06		
Part Number	N/A	Unit	N/A		
File Name	MCT-RACK-Series-MGM_Release note_1.02.0I_20200306.doc				

Release Note

FIRMWARE VERSION 1.02.0I	2
FIRMWARE VERSION 1.02.0H	2
FIRMWARE VERSION 1.02.0G	2
FIRMWARE VERSION 1.02.0F	2
FIRMWARE VERSION 1.02.0E	3
FIRMWARE VERSION 1.02.0D	3
FIRMWARE VERSION 1.02.0C	3
FIRMWARE VERSION 1.02.0B	4
FIRMWARE VERSION 1.02.0A	4
FIRMWARE VERSION 1.02.09	4
FIRMWARE VERSION 1.02.08	5
FIRMWARE VERSION 1.02.07	5
FIRMWARE VERSION 1.02.06	5
FIRMWARE VERSION 1.02.05	6
FIRMWARE VERSION 1.02.04	6
FIRMWARE VERSION 1.02.03	6
FIRMWARE VERSION 1.02.02	6
FIRMWARE VERSION 1.02.01	7
FIRMWARE VERSION 1.02.00	7

Firmware Version 1.02.0I

Date: 2020/03/06

New Feature / System Release	Description
N/A	N/A
Update	Description
RACK LED	Change that when click reset button, LED will blinking three times.

Firmware Version 1.02.0H

Date: 2020/02/27

New Feature / System Release	Description
N/A	N/A
Update	Description
System/WEB GUI	Fixed that when factory default then login web page will show “Setting changed” and still not saved issue.
SNMP	Fixed that use SNMP tool to setting TACACS server IP address will show setting success but result is not correctly issue.

Firmware Version 1.02.0G

Date: 2020/01/22

New Feature / System Release	Description
TACACS	Add that support TACACS function.
Update	Description
N/A	N/A

Firmware Version 1.02.0F

Date: 2019/12/16

New Feature / System Release	Description
N/A	N/A
Update	Description



Port Configuration	Fixed that when setting the speed of MCT-5002FSM module, it will fail issue.
--------------------	--

Firmware Version 1.02.0E

Date: 2019/12/13

New Feature / System Release	Description
N/A	N/A
Update	Description
SNMP	Fixed that when changing loopback port in MCT-5002FSM module via SNMP, it will not successful issue.
Port Configuration	Fixed that when setting the speed of MCT-5002FSM module, it will fail issue.
SFP Information	Fixed that SFP information with incorrectly issue in MCT-5002FSM module.
Module Configuration	Fixed that MCT-5002FSM module configuration can't work normal issue.

Firmware Version 1.02.0D

Date: 2019/11/27

New Feature / System Release	Description
Module Support	Added that system can support MCT-5002FSMSFP+ module.
Update	Description
Module Firmware	Fixed that the typo issue in MCT-2612 module.
Module Configuration / Dip Switch	Fixed that when enable dip switch the WEB still can configure this module issue.
RACK LED	Fixed that the LED with wrong behavior.

Firmware Version 1.02.0C

Date: 2019/05/02

New Feature / System Release	Description
N/A	N/A
Update	Description

Module Information	Fixed that SNMP module port link up and link down trap will random affect TX/FX information does not correctly.
--------------------	---

Firmware Version 1.02.0B

Date: 2019/04/25

New Feature / System Release	Description
N/A	N/A
Update	Description
Module Information	Fixed that SNMP module port link up and link down trap will random affect TX/FX information does not correctly.
Module Configuration / VLAN	Fixed that when insert/remove module will random cause setting config change to default value (e.g. VLAN configuration)

Firmware Version 1.02.0A

Date: 2019/04/18

New Feature / System Release	Description
N/A	N/A
Update	Description
Module Information	Fixed that SNMP module port link up and link down trap will random affect TX/FX information does not correctly.
Module Configuration / QinQ	Fixed that module QinQ ether type does not work on 0000-FFFF except for 8100, 9100, 9200.
Module Configuration / VLAN	Fixed that when insert/remove module will random cause setting config change to default value (e.g. VLAN configuration)

Firmware Version 1.02.09

Date: 2019/03/28

New Feature / System Release	Description
N/A	N/A
Update	Description
Module Information	Fixed that when WEB module information description key in %\ "? does not pop up error message.



SNMP Trap	Fixed that SNMP module port link up and link down trap does not show module name.
Module Information	Fixed that when insert old MCT-3002 module to MCT-RACK, module information will display two-stage.
SNMP Trap	Rename MCT-RACK12 SNMP fan trap to "case fan 1-4".
Digital Input/Output	Fixed that MCT-RACK module TP/FX digital output does not affect.

Firmware Version 1.02.08

Date: 2019/03/21

New Feature / System Release	Description
Hitless Reload	When reboot system will not reboot module. Notes: Before do reload system, if have configure still not save, then still will affect module port link down/up.
Update	Description
Module Information	Modify WEB module information Description should can't input %\ '?"
Module Configuration	Fixed that can't save configuration success even when module MCT-3612/MCT-2612/MCT-5002 TP port already saved.
System / WEB GUI	Fixed that when MCT-RACK is default configure, after connect MCT-3612 module, WEB GUI will display prompt "Settings changed, still not saved."

Firmware Version 1.02.07

Date: 2018/02/20

New Feature / System Release	Description
N/A	N/A
Update	Description
Configuration	Fixed that configuration fail issue on MCT-3612/2612 modules.

Firmware Version 1.02.06

Date: 2019/02/19

New Feature / System Release	Description
N/A	N/A
Update	Description

Link Alarm	Fixed that when Link Alarm is enabled with TP port disconnection on MCT-3612 module, the Fiber port will link up again issue.
------------	---

Firmware Version 1.02.05

Date: 2019/02/11

New Feature / System Release	Description
N/A	N/A
Update	Description
HTTPs	Fixed that when https enable, to save the settings and reboot, https does not work issue.

Firmware Version 1.02.04

Date: 2019/01/24

New Feature / System Release	Description
HTTPs	Added that HTTPs function.
Module	Support MCT-3002 series and MCT-100 modules.
Update	Description
N/A	N/A

Firmware Version 1.02.03

Date: 2018/12/19

New Feature / System Release	Description
N/A	N/A
Update	Description
IP address	Fixed that default gateway will disappear issue.

Firmware Version 1.02.02

Date: 2018/08/15

New Feature / System Release	Description
N/A	N/A
Update	Description
SFP	Fixed that the SFP speed value is incorrect issue.

Firmware Version 1.02.01

Date: 2018/07/24

New Feature / System Release	Description
N/A	N/A
Update	Description
System	Fixed that the system name will be showed incorrectly.

Firmware Version 1.02.00

Date: 2018/07/20

New Feature / System Release	Description
N/A	Release version 1.02.00 formal firmware and integrate the firmware of MCT-RACK-12-MGM and MCT-RACK-18-MGM.
Update	Description
N/A	N/A