

Model Name	CVT-SRC-5102SFP-MG	Version	1.00.07	Designer	Approval
Part Name	Firmware	Date	2025/05/08		
Part Number	N/A	Unit	N/A		
File Name	CVT-SRC-5102SFP-MG_Release note_1.00.07_20250508.doc				

Release Note

FIRMWARE VERSION 1.00.07	2
FIRMWARE VERSION 1.00.06	2
FIRMWARE VERSION 1.00.05	2
FIRMWARE VERSION 1.00.04	2
FIRMWARE VERSION 1.00.03	3
FIRMWARE VERSION 1.00.02	3
FIRMWARE VERSION 1.00.01	3
FIRMWARE VERSION 1.00.00	4

Firmware Version 1.00.07

Date: 2025/05/08

New Feature / System Release	Description
N/A	N/A
Update	Description
LED / Status	The Status LED now correctly blinks orange after releasing the hardware reset button during the reset to factory default stage.

Firmware Version 1.00.06

Date: 2025/05/05

New Feature / System Release	Description
N/A	N/A
Update	Description
Management / TACACS+	Changing the device hostname from the default value causes TACACS+ login failures.

Firmware Version 1.00.05

Date: 2025/04/24

New Feature / System Release	Description
N/A	N/A
Update	Description
Management / User Account	Using a user login password with up to 64 special characters will cause the web page to display a "502 Bad Gateway" error.
Management / RADIUS/TACACS+	Using the same username for both RADIUS/TACACS+ and the local user account will cause login failure.

Firmware Version 1.00.04

Date: 2025/04/16

New Feature / System Release	Description
System	Support for new hardware model "SRC-5102SFP-MG".
Update	Description
N/A	N/A



Firmware Version 1.00.03

Date: 2025/04/15

New Feature / System Release	Description
N/A	N/A
Update	Description
Management / User Account	Extending the maximum length of the user account password to 64 characters (including RADIUS and TACACS+).
TACACS+	Modify the "Remote address" parameter in the request to use the client IP address when communicating with the TACACS+ server for authentication, authorization, and accounting.
Switch Information	Using specific characters in the DHCP server option 12 host name may cause incorrect host name updates.

Firmware Version 1.00.02

Date: 2025/03/05

New Feature / System Release	Description
N/A	N/A
Update	Description
DHCP Client	DUT will update option 12 with previous input when there is no option 12 in current DHCP ACK packet.

Firmware Version 1.00.01

Date: 2025/02/26

New Feature / System Release	Description
DHCP Client	The device hostname can be assigned by the DHCP server using Option 12.
System Setup	System information supports a new parameter "Sync Host Name to System Name". Define: After being enabled, when the hostname is modified, the system will sync the same value to the system name (one-way).
Update	Description
System / WEB	Change DUT IP address will cause web page continue loading cannot stop.
CLI	"show interface detailed 1" via CLI will find has no "Collisions" field.
Reset System / WEB	When the user clicks the reload button through the web page, the



	browsing screen will not switch to the waiting page.
--	--

Firmware Version 1.00.00

Date: 2025/02/12

New Feature / System Release	Description
N/A	N/A
Update	Description
System	The Official Version.