



Model Name	XFS-5112	Version	1.00.03	Designer	Approval
Part Name	Firmware	Date	2025/08/18		
Part Number	N/A	Unit	N/A		
File Name	XFS-5112_Release note_1.00.03_20250818.doc				

Release Note

FIRMWARE VERSION 1.00.03	2
FIRMWARE VERSION 1.00.02	2
FIRMWARE VERSION 1.00.01	2
FIRMWARE VERSION 1.00.00	3



Firmware Version 1.00.03

Date: 2025/08/18

New Feature / System Release	Description
N/A	N/A
Update	Description
Performance / CLI	Improved execution performance of show running-config, start-up-config and default-config.
LLDP / System	When the user configures LLDP or checks the LLDP status, system midcore will crash.
CLI	Commands recorded through the terminal tool may contain a random number of spaces before the line breaks (CR/LF).

Firmware Version 1.00.02

Date: 2025/08/04

New Feature / System Release	Description
N/A	N/A
Update	Description
Restore Configuration / System	Restoring a configuration from a backed-up default-config failed, causing all ports to go down and the management IP address to change to 192.168.2.1 (accessible via console).
QoS / CLI	The "show qos" command displayed redundant wait prompt messages.
RSTP / WEB	In the Web RSTP status page, "Local Time of last Topology Change" was abbreviated as "Local Time of last TC".
CLI	When multiple commands are entered consecutively, some commands may randomly fail to execute.
SFP	Fixed an issue where the device failed to detect certain 10G multi-mode SFP modules.

Firmware Version 1.00.01

Date: 2025/08/04

New Feature / System Release	Description
N/A	N/A
Update	Description



N/A	Internal use.
-----	---------------

Firmware Version 1.00.00

Date: 2025/07/21

New Feature / System Release	Description
N/A	N/A
Update	Description
System	The Official Version.